

AMERICAN AIRLINES® QUALITY ASSURANCE ALERT

2009-06

May 26, 2009

TO: Class I, II, III, IV, TUL, AFW, MCI Maintenance Stations

SUBJECT: Revision to GPM Sections 05-04 and GPM 09-03

GPM sections 05-04 and 09-03 have been revised to address signature requirements for Aircraft Maintenance Technicians who do not hold fleet qualifications or task specific training.

Also addressed in this revision are new procedures for Aircraft Maintenance Technicians working under the guidance of Technical Services / MOD.

Please familiarize yourself with these new requirements to ensure that you are compliant with these revised procedures.

Original Signed By:

Barry Lederman
Manager Field QA

POSTED _____

REMOVED _____